


PARTS DIAGRAM



PARTS LIST

REF	DESCRIPTION	QTY
1	Lock pin 10	3
2	Pin shaft	2
3	Plain washer 22	2
4	Spring washer 22	2
5	Bolt M22*1.5	2
6	Pin shaft	1
7	Bottom weldment	1
8	Counter knife weldment	1
9	Nut M12	7
10	Bolt M12*30	7
11	Bolt M8*16	19
12	Counter knife	1
13	PTO cover	1
14	Bolt M6*20	8
15	Nut M6	10
16	Bracket	1
17	Bolt M14*1.5*45	8
18	Bearing UCFU208 with seat	2
19	Fly wheel weldment	1
20	Grease nipple	2
21	Knife	4
22	Rubber	2
23	Plate	1
24	Bolt M8*25	3
25	Nut M8	3
26	Hopper weldment	1
27	Nut M10	2
28	Top cover weldment	1
29	Lock pin 5	1

REF	DESCRIPTION	QTY
30	Washer	1
31	Washer	1
32	Washer	1
33	Bolt M6*25	2
34	Lock assemble	1
35	Discharge port assemble	1
36	handle 8*32	2
37	Nut M8	2
38	Bolt M8*16	4
39	Discharge port cover	1